GI

Global Inspection Services — Demo Organisation

Global Inspection Services (fictional demonstration organisation)

Consumer Products

Consumer Product Pre-Shipment Report

Moradabad Homeware Works

Moradabad · 4 Nov 2026

Client	Homecrest Retail Sourcing
Report number	GIS/RPT/2026/0026
Job reference	GIS/CP/2026/1040
Client reference	CLM-64505
Status	Issued

Table of contents

Section	Page
1. Client details	3
2. Vessel or asset details	3
3. Inspection details	3
4. Executive summary	3
5. Scope of work	3
6. Inspection findings	3
7. Inspection record	4
8. Tables and measurement schedules	5
9. Photographs	5
10. Conclusion and recommendations	6
11. Declaration	6
12. Limitations	6
13. Signatures	7
14. Annexures	7

1. Client details

Client	Homecrest Retail Sourcing
Address	Willingdon Island, Kochi
Client reference	CLM-64505
Contact	Sandeep Shah, Logistics Head

2. Vessel or asset details

Name	Moradabad Homeware Works
Address	Moradabad
Covered area (sq m)	3,900
Commodity stored	Metal homeware
Operator	Supplier (fictional)

3. Inspection details

Type of inspection	Pre-Shipment Inspection
Place	Moradabad
Commenced	4 Nov 2026, 11:20
Completed	4 Nov 2026, 18:40
Attending surveyor	Clara Jensen
Template	Consumer Product Pre-Shipment Inspection v1.0

4. Executive summary

At the request of Homecrest Retail Sourcing, we attended at Moradabad Homeware Works on 4 Nov 2026 to carry out a pre-shipment inspection of stainless steel vacuum flasks under job reference GIS/CP/2026/1040.

The order of 12,000 pieces was fully packed and presented. A sample of 315 pieces was drawn from 24 cartons. We found **no critical, 4 major and 9 minor defects**, which is within the limits agreed with the buyer. On-site checks were satisfactory.

5. Scope of work

Attend at Moradabad Homeware Works to carry out a pre-shipment inspection of stainless steel vacuum flasks on behalf of Homecrest Retail Sourcing, and report findings with supporting photographs.

The inspection was recorded on the template “Consumer Product Pre-Shipment Inspection”, version 1.0.

6. Inspection findings

Quantity. Cartons were counted against the packing list. All 500 cartons were present, each holding 24 pieces.

Sampling. Cartons were selected across the stack, including top, middle and bottom tiers, and the sample was drawn evenly across the three colourways.

Workmanship. Defects are listed in the schedule. The two flasks with stiff lid threads were traced by the factory to one moulding shift.

On-site checks. Carton drop, barcode scan, labelling and measurement checks were carried out on the sample and found in order.

7. Inspection record

Order

Factory	Moradabad Homeware Works
Client	Homecrest Retail Sourcing
Product description	Stainless steel vacuum flask, 750 ml, powder coated, three colours
Purchase order number	PO-ILLUS-48215
Style or item number	HC-VF-750
Order quantity	12000 pcs
Quantity packed and presented	12000 pcs
Share of order presented	100 %

Sampling plan

Inspection level	General level II
Sample size	315 pcs
Cartons opened	24
Acceptance limits applied	As agreed with the buyer: critical 0, major 10, minor 14 (illustrative)

Findings

Critical defects	0
Major defects	4
Minor defects	9
Total defects	13
Defects beyond agreed limits	No

Checks on site

Carton drop check	Pass
Barcode scan check	Pass
Labelling and marking against the order	Pass
Measurements against the specification	Pass

Result

Inspection result	Within agreed limits with remarks

8. Tables and measurement schedules

Measurement or result	Value	Basis
Share of order presented	100 %	Calculated
Total defects	13	Calculated

Calculated values use sample logic for illustration. They must be validated by a qualified person before they are relied on.

Defect list

#	Defect	Class	Quantity	Remarks
1	Coating chip on body, larger than 2 mm	Major	2	Blue colourway
2	Lid thread stiff, does not close by hand	Major	2	Reworked lot, see remarks
3	Light scratch on base	Minor	5	Not visible in normal use
4	Logo print slightly off centre	Minor	3	Within 2 mm
5	Gift box corner crushed	Minor	1	Outer carton sound

Measurement check

#	Point of measure	Specification	Tolerance	Sample 1	Sample 2	Sample 3
1	Overall height	265 mm	± 2 mm	265.4	264.8	265.1
2	Body diameter	73 mm	± 1 mm	73.2	72.9	73.0
3	Capacity to brim	750 ml	± 15 ml	756	751	748
4	Net weight	330 g	± 10 g	332	329	334

9. Photographs



Photograph 1: Coating chip on body, blue colourway



Photograph 2: Crushed corner on gift box



Photograph 3: Packed cartons presented for inspection



Photograph 4: Cartons selected for opening



Photograph 5: Shipping mark and barcode label on outer carton



Photograph 6: Sample units laid out by colourway

10. Conclusion and recommendations

The goods inspected were within the agreed limits at the time and place of inspection. We recommend that the factory re-checks the lid threads of the lot identified before loading and confirms the result to the buyer. This report relates only to the sample inspected and does not relieve the supplier of contractual obligations.

11. Declaration

We declare that this survey was carried out to the best of our knowledge and ability, that the findings recorded are a true account of the condition observed at the time and place of attendance, and that we have no interest in the subject matter other than as independent surveyors.

12. Limitations

This report is based on a visual inspection of accessible areas only. No dismantling, opening up or testing was carried out unless specifically stated. Calculations rely on documents and figures provided by the vessel or the client, which were accepted in good faith.

13. Signatures

Clara Jensen

Clara Jensen
Attending surveyor

Dr. Helen Abraham

Dr. Helen Abraham
Authorised signatory · 9 Nov 2026

Approval trail: Technical review by Capt. Mohan Iyengar on 8 Nov 2026; Department head approval by Capt. Dev Malhotra on 8 Nov 2026; Authorised signatory by Capt. Ashok Rane on 8 Nov 2026; Issue by Dr. Helen Abraham on 9 Nov 2026. Approved electronically in GetInspected.

14. Annexures

1. Nomination_J1040.pdf
2. Purchase_order_extract.pdf
3. Photograph register (6 images, originals retained)